



DOCUMENT NUMBER:
EFFECTIVE DATE:3/14/2021
PART NUMBER: BCDZF101

MSDS10001
Rev_A
SITE: San Diego

Safety Data Sheet: UWB1

Contents

1.	Identification of the hazard of substance.....	1
1.1	Product Name: UWB 1 (P/N BCDZF101).....	1
2.	Hazard Identification.....	1
2.1	Classification of the substance (GHS Classification).....	1
3.	GHS Label statement.....	1
3.1	General Advice.....	1

1. Identification of the hazard of substance.

1.1 Product Name: UWB 1 (P/N BCDZF101)

The product contains Spermidine
Final Concentration: 8.62mM
The use of the reference: Laboratory chemicals

2. Hazard Identification.

2.1 Classification of the substance (GHS Classification)

Skin Corrosion (Category 1B), H314
Serious eye damage (Category 1), H318

3. GHS Label statement.

Signal Word: Danger

Hazard Statement H314: Causes severe skin burns and eye damage.

Precautionary statements

Precautionary code	Precautionary Statements
P264	Wash skin thoroughly after exposure
P280	Wear protective gloves/clothing/eye protection/face protection
P301+P330+P331	If swallowed, rinse the mouth with water several times.
P305 + P351 + P338	<i>If inhaled, Rinse cautiously with water for several minutes.</i>
P310	Call a poison center
P363	Wash contaminated clothing before reuse
P501	Dispose of contents to an approved waste disposal plant

3.1 General Advice

Consult a physician. Show the MSDS to the doctor and receive proper treatment.